

葛尾村仮設焼却施設 令和3年12月 空間線量率測定結果

測定日	測定項目											
	空間線量率(μSv/h)											
	業務用地入口				業務用地北側				業務用地境界			
モニタリングポスト				モニタリングポスト				NaIシンチレーション式サーベイメータ				
朝	昼	夕	夜	朝	昼	夕	夜	東	南	西	北	
1	0.737	0.721	0.747	0.745	0.693	0.697	0.708	0.705	—	—	—	—
2	0.745	0.724	0.710	0.711	0.704	0.700	0.709	0.708	—	—	—	—
3	0.713	0.746	0.737	0.740	0.713	0.711	0.715	0.717	—	—	—	—
4	0.739	0.711	0.742	0.739	0.716	0.716	0.719	0.720	—	—	—	—
5	0.736	0.741	0.734	0.734	0.713	0.720	0.714	0.716	—	—	—	—
6	0.736	0.720	0.702	0.704	0.715	0.717	0.721	0.723	—	—	—	—
7	0.697	0.706	0.724	0.711	0.717	0.711	0.713	0.691	0.65	0.51	0.32	0.65
8	0.699	0.723	0.715	0.720	0.682	0.674	0.676	0.680	—	—	—	—
9	0.725	0.714	0.724	0.724	0.685	0.680	0.689	0.691	—	—	—	—
10	0.729	0.731	0.731	0.730	0.691	0.687	0.695	0.695	—	—	—	—
11	0.730	0.739	0.736	0.736	0.694	0.707	0.703	0.705	—	—	—	—
12	0.737	0.745	0.743	0.744	0.706	0.715	0.715	0.713	—	—	—	—
13	0.735	0.694	0.709	0.710	0.708	0.704	0.707	0.711	—	—	—	—
14	0.708	0.655	0.633	0.634	0.711	0.712	0.714	0.716	0.65	0.51	0.34	0.66
15	0.636	—	—	—	0.717	—	—	—	—	—	—	—
16	—	—	—	—	—	—	—	—	—	—	—	—
17	—	—	—	—	—	—	—	—	—	—	—	—
18	—	—	—	—	—	—	—	—	—	—	—	—
19	—	—	—	—	—	—	—	—	—	—	—	—
20	—	—	—	—	—	—	—	—	—	—	—	—
21	—	—	—	—	—	—	—	—	0.68	0.53	0.34	0.66
22	—	—	—	—	—	—	—	—	—	—	—	—
23	—	—	—	—	—	—	—	—	—	—	—	—
24	—	—	—	—	—	—	—	—	—	—	—	—
25	—	—	—	—	—	—	—	—	—	—	—	—
26	—	—	—	—	—	—	—	—	—	—	—	—
27	—	—	—	—	—	—	—	—	—	—	—	—
28	—	—	—	—	—	—	—	—	0.66	0.51	0.31	0.63
29	—	—	—	—	—	—	—	—	—	—	—	—
30	—	—	—	—	—	—	—	—	—	—	—	—
31	—	—	—	—	—	—	—	—	—	—	—	—

備考 12/15 施設の解体撤去に伴い、モニタリングポストの機器を撤去。測定終了。

