放射能濃度測定結果 平成27年度												
	粉じん放射能濃度(Bq/m³)											
測定月	川内村 下川内仮置場											
	測定場所:仮置場周囲											
	東			北			西			南		
	¹³⁴ Cs	¹³⁷ Cs	合計									
4	ND	ND	_	ı	_	_	ND	ND	_	_	_	1
5	ND	ND	-	1	-	-	ND	ND	-	-	_	1
6	ND	ND	-	1	-	-	ND	ND	-	-	_	1
7	ND	ND	-	1	_	-	ND	ND	-	-	_	-
8	_	-	_	ND	ND	-	_	_	_	ND	ND	_
9	_	-	-	ND	ND	-	-	-	-	ND	ND	-
10	_	-	-	ND	ND	-	-	-	-	ND	ND	-
11	ND	ND	_	_	_	-	ND	ND	_	_	_	_
12	_	_	_	ND	ND	_	_	_	_	ND	ND	_
1	ND	ND	_	-	_	_	ND	ND	_	_	_	_
2	_	_	_	ND	ND	_	_	_	_	ND	ND	-
3	_	_	_	ND	ND	_	_	_	_	ND	ND	_

ND:通常の定量限界値未満