

## 放射能濃度測定結果 平成27年度

測定月	粉じん放射能濃度(Bq/m <sup>3</sup> )											
	南相馬市 大富仮置場											
	測定場所：仮置場周囲											
	北東			南東			南西			北西		
	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計
4	—	—	—	—	—	—	ND	ND	—	ND	ND	—
5	ND	ND	—	—	—	—	ND	ND	—	—	—	—
6	ND	ND	—	—	—	—	ND	ND	—	—	—	—
7	ND	ND	—	—	—	—	ND	ND	—	—	—	—
8	ND	ND	—	—	—	—	ND	ND	—	—	—	—
9	ND	ND	—	—	—	—	ND	ND	—	—	—	—
10	ND	ND	—	—	—	—	ND	ND	—	—	—	—
11	北			東			南			西		
	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計
	ND	ND	—	—	—	—	ND	ND	—	—	—	—
12	北東			南東			南西			北西		
	ND	ND	—	—	—	—	ND	ND	—	—	—	—
1	ND	ND	—	—	—	—	ND	ND	—	—	—	—
2	ND	ND	—	—	—	—	ND	ND	—	—	—	—
3	ND	ND	—	—	—	—	ND	ND	—	—	—	—

ND:通常の定量限界値未満