

| 放射能濃度測定結果 平成25年度 |                   |                   |    |
|------------------|-------------------|-------------------|----|
| 測定月              | 地下水放射能濃度 (Bq/L)   |                   |    |
|                  | 南相馬市 角部内仮置場       |                   |    |
|                  | 測定場所：観測井          |                   |    |
|                  | <sup>134</sup> Cs | <sup>137</sup> Cs | 合計 |
| 4                | -                 | -                 | -  |
| 5                | -                 | -                 | -  |
| 6                | -                 | -                 | -  |
| 7                | -                 | -                 | -  |
| 8                | -                 | -                 | -  |
| 9                | ND                | ND                | -  |
| 10               | ND                | ND                | -  |
| 11               | ND                | ND                | -  |
| 12               | ND                | ND                | -  |
| 1                | ND                | ND                | -  |
| 2                | ND                | ND                | -  |
| 3                | ND                | ND                | -  |

ND: 通常の定量限界値未満