

## 放射能濃度測定結果 平成27年度

測定月	粉じん放射能濃度(Bq/m <sup>3</sup> )											
	南相馬市 角部内仮置場											
	測定場所：仮置場周囲											
	北			東			南			西		
	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計
4	ND	ND	—	—	—	—	ND	ND	—	—	—	—
5	ND	ND	—	—	—	—	ND	ND	—	—	—	—
6	—	—	—	ND	ND	—	—	—	—	ND	ND	—
7	—	—	—	ND	ND	—	—	—	—	ND	ND	—
8	ND	ND	—	—	—	—	ND	ND	—	—	—	—
9	ND	ND	—	—	—	—	ND	ND	—	—	—	—
10	ND	ND	—	—	—	—	ND	ND	—	—	—	—
11	—	—	—	ND	ND	—	—	—	—	ND	ND	—
12	ND	ND	—	—	—	—	ND	ND	—	—	—	—
1	—	—	—	ND	ND	—	—	—	—	ND	ND	—
2	ND	ND	—	—	—	—	ND	ND	—	—	—	—
3	—	—	—	ND	ND	—	—	—	—	ND	ND	—

ND:通常の定量限界値未満