

## 放射能濃度測定結果 平成26年度

測定月	粉じん放射能濃度 (Bq/m <sup>3</sup> )											
	檜葉町 井出仮置場											
	測定場所：仮置場周囲											
	東			北			西			南		
	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計
4	ND	ND	-	-	-	-	ND	ND	-	-	-	-
5	-	-	-	ND	ND	-	-	-	-	ND	ND	-
6	ND	ND	-	-	-	-	ND	ND	-	-	-	-
7	ND	ND	-	-	-	-	ND	ND	-	-	-	-
8	ND	ND	-	-	-	-	ND	ND	-	-	-	-
9	ND	ND	-	-	-	-	ND	ND	-	-	-	-
10	ND	ND	-	-	-	-	ND	ND	-	-	-	-
11	ND	ND	-	-	-	-	ND	ND	-	-	-	-
12	ND	ND	-	-	-	-	ND	ND	-	-	-	-
1	ND	ND	-	-	-	-	ND	ND	-	-	-	-
2	ND	ND	-	-	-	-	ND	ND	-	-	-	-
3	ND	ND	-	-	-	-	ND	ND	-	-	-	-

ND: 通常の定量限界値未満