

## 放射能濃度測定結果 平成27年度

測定月	粉じん放射能濃度(Bq/m <sup>3</sup> )											
	檜葉町 前原第三仮置場											
	測定場所：仮置場周囲											
	東			北			西			南		
	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計	<sup>134</sup> Cs	<sup>137</sup> Cs	合計
4	ND	ND	—	—	—	—	ND	ND	—	—	—	—
5	—	—	—	ND	ND	—	—	—	—	ND	ND	—
6	ND	ND	—	—	—	—	ND	ND	—	—	—	—
7	—	—	—	ND	ND	—	—	—	—	ND	ND	—
8	ND	ND	—	—	—	—	ND	ND	—	—	—	—
9	—	—	—	ND	ND	—	—	—	—	ND	ND	—
10	ND	ND	—	—	—	—	ND	ND	—	—	—	—
11	ND	ND	—	—	—	—	ND	ND	—	—	—	—
12	—	—	—	ND	ND	—	—	—	—	ND	ND	—
1	ND	ND	—	—	—	—	ND	ND	—	—	—	—
2	ND	ND	—	—	—	—	ND	ND	—	—	—	—
3	—	—	—	ND	ND	—	—	—	—	ND	ND	—

ND:通常の定量限界値未満